






Date Originated: 05/12/06	Revision: A	Revision Date:	Standards No. 500041-XX
Subject: VDO Programmable Tachometer Lamp Replacement Instructions			

Replacing the Wedge Lamp

1. Turn and pull lamp socket to remove it from gauge housing. This may require the use of pliers (see diagram).
2. Pull wedge lamp straight out to remove it from socket.
3. Replace with new lamp.
4. Press lamp socket straight into gauge housing until it snaps into place.



Gauge Lamp Accessory Kits

Description	Voltage	VDO Part No.	IC Kit No.	
2 Wedge Lamps	12V	600 815	4050352	
2 Wedge Lamps	24V	600 826	4050353	
2 Lamp Sockets	-	600 840	4050354	