



**TECHNICAL BULLETIN  
No. 0124**

**FOAM MANAGER DISCONTINUED  
ECLIPSE® CAFSYSTEM CHANGE**

Waterous announces changes to the Foam Manager System and the Eclipse® CAFSystem.


Beginning July 10, 2017, the Foam Manager System will be discontinued.

Beginning on July 1, 2017, all orders received for Eclipse CAFSystems will only be available with the updated AQUIS Foam Proportioning Systems and either the new compact foam manifold (**see Figure A and Sales Bulletin 0110**) or the existing flowmeter tees and optional master waterway check valves.

Additional changes affecting the Eclipse CAFSystems are as follows:


- Foam Manifold will now be shipped loose and will no longer be offered as an assembled part of the Eclipse CAFSystem.
- New compact foam manifold is shorter than previous models (**see Figure A**) and will require the OEM to provide the necessary support brackets and plumbing for installation to the fire pump (**see Figures B and C**).

Figure A. Foam Manifolds



CAST IRON  
WEIGHT AS SHOWN: 31lbs

Figure B. Eclipse CAFSystem Prior to 7/10/17    Figure C. Eclipse CAFSystem After 7/10/17



*NOTE: The information in this technical bulletin was current at the time of printing. Waterous reserves the right to change this information*